

Measurement and Documentation for Structural Integrity Assessment of an In-Service School

Building at Risk

J. O Ehiorobo^a, O. C. Izinyon^b and R. O. Ogirigbo^c

Department Of Civil Engineering, University Of Benin, Benin City (NIGERIA)



ABSTRACT

- ❖ The primary aim of carrying out structural integrity assessment of an in-service building is to determine the extent of damage or extent of distress at any point in time.
- ❖ This paper examines the methods adopted for damage detection in a school building in Benin City Nigeria.
- ❖ The methods adopted included visual inspection, measuring, photographing, probing and sampling.
- ❖ Bearing capacity of soil at the foundation of columns were examined using Dynamic Cone Penetrometer Tests along with normal boring with bearing capacity estimated from results of laboratory tests.
- ❖ Position, direction, width and extent of cracks in various parts of the building were measured.
- ❖ An As-Built plan of the building was prepared from total station survey of the building.
- ❖ Elevation within the building area were measured to determine the direction of slope in order to estimate the effect of wetting on the building foundation
- ❖ The results of the tests were used to build a database for the development of remedial measures which will increase the service life and safety of the building structure.



INTRODUCTION

- ❖ Structural integrity assessment is a process by which we determine how reliable an existing structure is able to carry current and future loads
 - and fulfil the task for a given time period.
 - ❖ In structural monitoring, periodic measurement of displacement, strains, stresses, damage evaluation (e.g. crack width) and vibration characteristics are carried out
 - with the sole objective of either detecting the changes that have taken place in the structure or
 - where the structure appears to be at risk to plan for its evacuation.
- 

- ❖ When there are noticeable defects in the structure such as visible cracks in a building,
 - a study to determine the condition of the building is carried out.
 - ❖ Such investigation should identify the type of defect such as cracking and subsidence, settlement or movement of the structure.
 - ❖ Technical expertise and an understanding of building construction is essential to correctly identify the cause of building defects and
 - the remedial measures required to put the defects right.
- 

- ❖ Building inspection is a general surface examination of those parts of a property which are accessible.
- ❑ In order to carry out the inspection,
- ❑ the surveyor requires some basic equipment to be used during the survey.
- ❑ In general four types of inspection are distinguishable:
 - ❖ these include visual inspection, concealed object inspection, Dampness inspection,
 - ❖ stress and strain survey.

- ❖ In visual inspection, the equipment include
 - digital camera, binoculars, magnifying glass, video recorder etc.
- ❖ Concealed object inspection may be carried out by the use of
 - cover meter, fibrescope, endoscope etc.
 - Dampness inspection may be carried out using digital thermometer, hygro test kit, wheel etc.

- ❖ Stress and strain tests are carried out to test the structural integrity of various component of the building structure.
- They enable for the detection of sources of bending, cracks and displacement in the structures.
- ❖ Some of the equipments for this test include
 - strain gauge,
 - ultrasound and
 - Geodetic survey methods.

- ❖ Cracks develop in a building or sections of a building whenever stress in the component exceeds its strength.
- ❖ Stress in the building component may be caused by externally applied forces such as
 - dead and live load or foundation settlement or
 - it could be induced internally by thermal variation, moisture changes, chemical actions etc.
- ❖ A proper understanding of the type of movement that has caused the crack, and the rate at which this movement is to be expected in the future,
 - is a key step in analysing and providing specifications for the repairs of the cracks.
- ❖ Buildings can move in several directions and this movement can be in various forms.

- ❖ It could be the building moving itself,
 - or a small portion of it,
 - or it could be the soil on which the building is built, or a small portion of it.
- ❖ Thus, crack is not the cause, but rather the sign that shows that the building is undergoing movement.
- ❖ There are two major reasons why buildings move, and they include:
 - Movement as a result of conditions below ground; and
 - Movement as a result of conditions above ground.

❖ **SITE DESCRIPTION**

- ❖ St. Mary dedication international school is located along Sapele road in Benin City
- ❖ at a distance of about 0.75Km from the city centre.
- ❖ The school consist of blocks of classrooms, offices and dormitories.
 - ❑ The layout of the building at the school is shown in Fig 1
 - ❑ while the attribute descriptions of the building are shown in Table 1.

Table I: Attribute Characteristics of School Building

Block – ID	Floors (Nos)	Uses
Block - A	4	Offices, classroom, Laboratories and dormitory
Block - B	3	Offices and classroom
Block - C	2	Ceremonial and Assembly hall
Block - D	3	Offices and classroom
Block - E	3	Kitchen, offices and stores




Fig 1: LAYOUT OF BUILDINGS IN SCHOOL

- ❖ There are five blocks of buildings within the school compound.
- Shear cracks are noticeable in many of the buildings particularly block A
- which is multi functional block having offices, classrooms, Laboratories and dormitories.
- The cracks are more noticeable on the west wing of the building separated by expansion joint.
- Most of the cracks run from the first floor to the roof.

Data Collection.

- ❖ The first phase of work involved a review of the original designs and
- ❖ construction documents and drawings with the necessary approval by the Edo Development and Property Authority (EDPA).

These were used to:

- Assess the structural layout of the buildings
- Identify critical areas for inspection
- Identify the specified loads to assess usage and possibility of overloading.
- Verify if unauthorised addition or alteration have been carried out in the building structures.

✓ Based on these evaluations, the following field surveys were carried out:

- I. Topographical survey of the project site
- II. As- Built surveys of the buildings.
- III. Geotechnical investigation within the building area and Georeferencing of borehole and CPT locations.
- IV. Visual inspection of building
- V. Measurement of crack width and length.
- VI. Rebound hammer tests on concrete column.

Visual Inspection

- Visual inspection of various parts of the building show that Block A has sufficiently suffered serious structural deterioration.
- Several cracks both longitudinal and transverse were observed particularly in the west wing of the block.
- Many of the cracks run from the ground floor to the roof. Photographic images of many of the cracks are shown in fig 3 to fig 8.



Fig 3: crack in office wall



Fig 4: crack along outside Column D4



Fig 5: Crack around Beams



Fig 6: major crack in wall



Fig 7: diagonal crack on wall



Fig 8: crack in Window

❖ Topographical and As-Built Details

The total station survey results were used to develop a 3D terrain model of the site
▪ in order to determine the direction of runoff.

- ❖ The purpose of the survey was to determine if the percolation of storm water in to the ground at the foundation of the building
- ❖ is responsible for weakening of the soil and creating differential settlement.







Table II: SAMPLING POINTS COORDINATES

S/N	Borehole No.	NORTHING	EASTING
1	BH 1	255705.126	355611.103
2	BH 2	255672.550	355635.118
3	BH 3	255643.349	355604.164
4	BH 4	255654.869	355559.144
5	BH 5	255668.597	355553.450
6	BH 6	255659.494	355595.450
7	BH 7	255680.397	355568.598
8	CPT 1	255702.777	355607.655
9	CPT 2	255648.049	355592.627
10	CPT 3	255659.595	355556.686
11	CPT 4	255629.595	355583.672

- ❖ From the structural analysis point of view,
 - the isolated footings existing in the site are expected to have a maximum settlement varying from
 - 13.88 to 104.89mm with an average of 53.66mm
 - and the maximum differential settlement about 91.01mm
 - in standard practice, allowable differential settlement should be 25mm
 - and the maximum differential settlement is limited to half of the total allowable settlement i.e. 12.50mm.

- A plot of the differential settlement – duration curve is shown in fig 11 below.




Fig :11 Settlement-duration chart for the foundation footing

- ❖ In the site under consideration, there is a considerable amount of clay content in the soil
- ❖ and the clay is likely to be saturated.
- ❖ In such case, settlement is likely to occur over a period of about 25years;
- ❖ and within 5years maximum differential settlement would have reached 40mm.
- ❖ As a result, structural distress would have become noticeable
- ❖ as evidenced from the different types of cracks (both longitudinal and transverse)
- ❖ and map shaped cracks noticeable in Block A.

- ❖ From an evaluation of the geotechnical results,
 - the defects at the site can be said to have resulted from inadequate foundation consideration
 - as the foundation has been designed on a consolidating soil strata
 - with high differential settlement.

Crack Measurement

- ❖ From the measurement carried out in block A on the major cracks,
 - the longest of the cracks occurred along the column joint with the cracks varying from a minimum of 1.8m to 3.15m.
 - The width of the cracks ranged from 1.75mm to 22.25mm.
- ❖ Along the walls, the length of the cracks varied from 525mm to 2800mm
 - while the width varied from 15.50mm to 31.50mm.
- ❖ Diagonal cracking was found to be approximately 1.2m in length
 - and initiated at about 0.55m from the support.
- ❖ In general, cracks vary in size from 0.75mm to 31.50mm.
- ❖ The results of both visual inspection and instrumental measurement
 - does show that extensive crack development and propagation occurred on the ground floor slab, columns and walls on every floor in block A.

❖ **Assessment of Concrete Strength Using Rebound Hammer.**

- ❑ Results of non destructive strength assessment of columns, beams and slabs using Schmidt Hammer tests are summarized in table 3 below:

Table 3: summary of Non destructive Tests of structural Elements.

S/N	Structural Element	Member	Mean compressive strength N/mm ²
1	Column	D1	41
2	Column	D2	43
3	Column	D3	42
4	Column	D4	40
5	Beam – first Floor	D14	57
6	Beam – Second Floor	D14	50

- ❖ In table 3, the mean compressive strength for each of the structural element was $> 25\text{N/mm}^2$ which is the minimum acceptable compressive strength of concrete.

CONCLUSION

- ❖ This study has been carried out using a combination of
- ❖ structural, Geotechnical and Geomatics Engineering methods.
- ❖ From the investigation carried out,
 - it has been established that inadequate foundation consideration has resulted in differential settlement
 - which is responsible for the various cracks noticeable in building Block A.
- ❖ The foundation footing is found to be inducing high bearing pressure on the soil,
 - thus resulting in substantial differential settlement.

The cracks within the building vary in width from 0.75mm to 31.50mm.

- ❖ As some of the cracks along the wall are more than 25mm,
- ❖ it means that the stability of the building is already being impaired.
- ❖ As these cracks taper and extend below doors and windows openings in many cases,
- ❖ we can conclude that the cracks has occurred as a result of differential settlement.



THANK YOU FOR LISTENING.

