Enrico Davoli

Keywords: Engineering survey; gnss/gps; emergency conditions

Summary:

Climate change and human intervention have resulted unfortunately into unprecedented catastrophic events. During the aftermath of these events, what can a surveyor's main role be?

This paper aims to illustrate the different phases we undertook in these natural catastrophic events. It is essential to establish technical pathways concerning science, technical knowledge, and experience, especially during the first critical and emergency phases. It is also important to highlight the importance of our involvement as surveyors, the attitude to maintain, both in the personal and professional perspectives, whenever we work alongside rescue facilities. In this way, we play a crucial role in monitoring and data planning.

1. Introduction:

This paper concerns some of my professional experiences carried out in emergency phases with the aim of highlighting the need to establish smart and practical operating protocols aimed at improving the technical support of the emergency structures.

2. Subtitle:

In the last 30 years there have been 5 shipwrecks of large cruise ships or medium-sized boats and more than 632 earthquakes. Since our work is a crucial part of managing these emergencies, it is becoming increasingly necessary to analyze the events that are taking place in the world, also due to human errors and the role that the alerted technical figures have played.

In my short career I have had the opportunity to cooperate during the following catastrophic events:

2.1 Costa Concordia Survey:

Following the sinking of the Costa Concordia cruise ship on 13/01/2012 off the island of Giglio (Gr), some surveyors belonging to the National Council of surveyors and graduate surveyors of the province of Grosseto were alerted and summoned by the command of the fire brigade and civil protection of the province of Grosseto in order to install the first site for monitoring the position of the ship. This was accomplished by installing a total station and two prisms, one forward and one aft. This survey was aimed at monitoring the slipping and settling of the ship towards the underlying 70-meter abyss which would have inevitably dragged the rescuers intent on the rescue operations with them.

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli



Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli



Following the operational difficulties in maintaining a constant monitoring with a total station also due to unfavorable weather conditions, I and another colleague, who are part of the board of surveyors and graduate surveyors of Modena, were activated and we reached the island del Giglio in order to provide for the installation of a second site for monitoring the ship using gps instrumentation in rover-gps methodology.

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli



The monitoring lasted 3 weeks: the first week for 24 hours a day, while the other two only during the day since rescue activities were limited.

2.2 Emilia Romagna earthquake:

The 2012 Emilia earthquake was a seismic event (magnitude 5.9 and 5.8) consisting of a series of shocks located in the seismic district of the Emilian Po Valley, mainly in the provinces of Modena, Ferrara, Mantua, Reggio Emilia, Bologna and Rovigo, but also felt in a very large area including all of central-northern Italy, between 20 and 29 May 2012.

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli

Following this catastrophic event, the civil protection, in agreement with all the public safety commands (firefighters, police, etc.), proceeded to extraordinary request the intervention of numerous professionals including surveyors belonging to the board of surveyors and graduate surveyors from the province of Modena with 2 main purposes:

- the mapping and census of the first reception camps;

- the survey and census using specific forms of the static and structural conditions of the buildings located within the municipalities.

The first survey and census phase took place using GPS instrumentation in Rtk aimed at framing and census the positioning of the first reception camps and the related equipment.



Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli



Afterwards, the survey was rendered graphically in 2D and delivered to the heads of the civil protection who would have implemented or modified the equipment present in the fields.

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli



The second aim was drawn up directly by the civil protection together with the professional orders and concerned the census of the damaged buildings by means of a visual and technical inspection. Specifically, the buildings have been divided into 3 macro-categories:

- homes and small commercial buildings;
- listed or valuable assets, such as churches, sanctuaries or monasteries;
- large structures or complicated structures, such as large silos or vertical warehouses.

The classification of the damaged buildings was carried out with the aid of three types of technical sheets for expeditious compilation, called AEDES sheet.

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli

"Ordinary" buildings:

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli

hesidenza del Consiglio dei Ripartimento della Protecio	Hill vi et di e Giwille			ID SCHEDA:			DB	NFERENZA DELLE RESI LO N LE PROVINCE AUTONOME				
			SEZIONE1 - II	DENTIFICAZIO	IF EDIFICIO							
rovincia:			SELIONET - II		100000000000000000000000000000000000000							
omune:				1.5.00.000	IDENTIFICATIVO SOPRALLUOGO giorno mese anno Squadra 1 1 Scheda n. 1 Data 1 1 1							
razione/Località	Service				ICATIVO EDIFICIO							
(denominazione Istat) 1 O VIA					I Istat Reg. 11 Istat Prov. 11_1 Istat Comune 11_1							
O PIAZZA				Cod. di	Cod. di Località Istat III Tipo carta Sez. di censimento Istat II N° carta II Dati catastali Foglio II Allegato II							
O ALINO	(Indicare	contrada, localita,	traversa, salita, etc.)	Sez. di c								
COORDINATE	O piane UTM O	geografiche O	altro	Dati ca								
Fuso	San Share and Share a	1/Lat <u> </u>		_I Particel			ILLL	<u> </u>				
5/9	O ED50						~ ~ ~ ~					
	the second second			_I Posizio	ne edificio O l							
ENOMINAZIONE	EDIFICIO O PROPRI	ETARIO I_I_I						ource use				
				2010 - 2010 - 2010 201			SHE AREAD					
APPA DELL'AGG	REGATO STRUTTUR	ALE CON IDENTIFIC	AZIONE DELL'EDIFICI	0			12 12 12 12					
_		10 10 10 10										
			<u></u>									
+-+-+		8 8 8 8		8 8 8 8								
		8 8 8 8	<u></u>				21 21 21 21	21 21 21 21				
		2 2 2 2	<u> </u>	<u>e-e-e-e</u>	<u> </u>	<u></u>						
		2 2 2 2		2-2-2-2	2 2 2 2							
		S 8 8 8										
	B -11		SEZIONE 2 -	DESCRIZION	E EDIFICIO							
		metrici		Età (max 2)	-		sposizione					
N° Piani totali con interrati	Altezza media Superfi di piano (m) di pia			Costr. e ristr.	Uso	N° unità d'uso	Utilizzazione	Occupanti				
	COLUMN STREET	di piano (m²) A Q < 50 I Q 400 ÷ 499		1 🗖 < 1919 2 🗖 19 ÷ 45	A 🗖 Abitativo							
01 09	1 O < 2.50 2 O 2.50 ÷ 3.49	B Q 50 ÷ 69	L Q 500 \div 649	3 🗖 46 ÷ 61	8 D Produttivo C D Commercio		A Q > 65% 8 Q 30÷65%	·				
03 011	1 O 3.50 ÷ 5.00	c Q 70 ÷ 99	M Q 650 ÷ 899	4 🗖 62 ÷ 71 5 🗖 72 ÷ 75	0 🗖 Uffici		C Q < 30%					
04 0 12	4 O > 5.00	D O 100 ÷ 129	N 🔿 900÷1199	6 76 ÷ 81	E 🗖 Serv. Pubbl.		0 O Non utilizz.					
0 5 O >12		E 🔿 130÷169	0 ○ 1200 ÷ 1599	7 🗖 82 ÷ 86	F 🗖 Deposito		E 🔾 In costruz.					
06	Piani interrati	F 🔿 170 ÷ 229	P () 1600 ÷ 2199	8 🗖 87 ÷ 91 9 🗖 92 ÷ 96	G 🗖 Strategico		F 🔾 Non finito					
07	100 002	6 O 230 ÷ 299	Q Q 2200 ÷ 3000	9 0 92 ÷ 96	H 🗖 Turist-ricett.		G 🔿 Abbandon.	9				
08	8 O 1 0 O 23	H () 300÷399	R (O > 3000	11 🗖 02 ÷ 08		Proprietà	A 🗂 Pubblica	B 🗖 Privata				
		1		12 🗖 09 ÷ 11	1							

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli

Buildings "large dimensions":

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli

	n interrati di piano (m.) di piano (m²) n interrati 0 <3.50 A O ≤200 L O 2500+3000		eristruttur	azione			unitàd′uso iale III A⊙>65%			ordinari					
N° Piani totali	Altezza med	a	Sup	erficie me		Costruzi	one	Uso		Numero		Utilizzazione		Occupanti	
		Dati met	rici		SEZIONE	2A - DESCI Età (ma		E EDIF	ICIO	lls) - ASI	osizio	ne		
					CETIONE				1010						1 2 1
							-								
									144	11		11			
APPRESENTAZ	IONE SCHEMA	TICA DELL	EDIFICIO	CONISU	IOI BLOCCHI A	GGIUNTI COD	FICAT	1							
ASSE D'USO EDIFICIO 10 Classe I 20 Classe II 30 Classe III				40 Class	Classe IV						181				
NOMINAZION	E EDIFICIO O P	ROPRIETA	RIO II				<u> </u>							CODIC	E USO
	O WGS84	Long./E	st II			יןטבי					- mu		- 2 over210		5 ang
2-33-34)	O ED50						PASIZI		FICIO 1/2) Isolate 9	O let	orno 2/) D'estremi	H 10	D'anm
000RDINATE O piane UTM (m) O geografiche (°) O altro uso Datum Lat./Nord															
ORDINATE) niane LITM	(m) 🔾 a	reografic	he (°) () altro		DATI CATASTALI - PARTICELLE								
O ALTRO	6	Indicare co	ntrada, le	ocalità, tr	aversa, salita,	etc.)									
2 O CORSO						IDENTIFICATIVO EDIFICIO Nº aggregato _ _ _ _ _ Nº edi					N° edifi	ificio _ _ _			
O VIA		ĻĻļ	<u></u>									- 1			
razione/Localit denominazione							Squadra	Ш	_l_l Sch	edan.l <u>l</u>	1/1	11	l Data 🔤		11
Comune:					giomo mese anno										
rovincia:							- IDENTIFICATIVO SOPRALLUOGO								
					SEZIONE 1	- IDENTIFI	CAZIO	NE EDI	FICIO						
NALISI EDIF	1010					ID	SCHEE	A:							
sidenza del Consiglio d artimanta della Protezi	ces Civile		Gru	opo di Lav	voro - Decreto d				827 del 5 m	arzo 2012					
there is a first of the second second			En ED	1 101 1		GL-AeDES 0	11/201	41	12.7.107.0				CONFE	RENZA DEL	LE REGION
OTEZIONE	0	P	FR FD	FICI A	STRUTTU	RA PREFA	ABBR	IC ATA	O DI GR	ANDE L	ICE				

				and future of	eee copronizione					
N° Piani totali con interrati	Altezza media di piano (m)	Superficie media di piano (m²)		Costruzione e ristrutturazione	Uso	Numero unità d'uso	Utilizzazione	Occupanti ordinari		
01 02 03 04 025	 ○ <3.50 ○ 3.5+4.99 ○ 5.0+6.99 ○ 7.0+9.99 ○ 10.0+14.00 ○ >14.00 	A ○ ≤200 B ○ 200+250 C ○ 250+300 D ○ 300+400 E ○ 400+500 F ○ 500+650 G ○ 650+900	L C 2500+3000 M C 3000+3500 M C 3500+4000 O C 4000+4500 P C 4500+5000 Q C 5500+6000 R C 6000+7000	$1 \Box \le 1950$ $2 \Box \le 51+61$ $3 \Box \le 62+71$ $4 \Box \le 72+75$ $5 \Box \le 76+81$ $6 \Box \le 82+86$ $7 \Box \le 87+91$	A Residenziale B Produttivo C C Commercio D Utfici E Serv. pubbl. F D Deposito G S trategico		A ○ >65% B ○ 30+65% C ○ <30 D ○ Nonutilizz E ○ In costruz F ○ Non finito G ○ Abbardonato	Luluuluuluu		
Piani interrati A O 0 B O 1 C O 2 D O 23	Altezza massima libera pilastri J	H 🔾 900+1200 I 🔾 1200+1600 J 🔾 1600+2000 K 🔾 2000+2500	S ⊙ 7000+10000 T ⊙ 10000+15000 U ⊙ 15000+20000 V ⊙ >20000	$8 \Box \le 92+96$ $9 \Box \le 97+01$ $10 \Box \le 02+08$ $11 \Box \le 09+11$ $12 \Box > 2011$	H 🗆 Turist. ricett. I 🗆 Parcheggio J 🗔 Attr. sportive K 🗔 Spaziespos.		Propr A 🗆 Pubblica	1.2250 2.5257 2.55577		

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)

Enrico Davoli

All the activities carried out by the surveyors enrolled in the provincial College of Surveyors and Graduate Surveyors of the province of Modena were carried out on a voluntary basis and without receiving compensation in order to help the populations affected by the earthquake.

3. Discussion

Following the work carried out, I was able to ascertain how fundamental organization is in these catastrophic and emergency conditions and how essential it is to follow clear and standardized guidelines in order to optimize the information collected and deliver reliable data to the responsible authority who will then be able to define the most appropriate use.

4. Conclusion

Never as in these periods of climate and environmental change is it necessary to be ready, especially in an emergency, to provide one's professional contribution quickly and efficiently.

It is necessarily to create, in agreement with international corps, a database of working methods and approaches to emergency conditions also on the basis of the morphological characteristics of one's own territory, in order to be able to direct the professionals of the future, who will find themselves in our same situations of emergency, to proceed efficiently in supporting the rescue and civil protection teams.

It would be interesting to create a pool of surveyors who could locally support the Onu or the Unher in the early post-emergency phases through protocols shared with the civil protection company of the various states and with the best technologies that our profession offers (laser scanners, drones, thermal camera , etc.) in order to be able to direct other volunteer professionals of the emergency site to have a standardized protocol to follow.

REFERENCES CONTACTS ENRICO DAVOLI VIA TOBAGI 15 MODENA ITALY Tel. + 393396684282 Email: <u>enricodavoli134@gmail.com</u>

Be a Surveyor in Emergency Conditions Shipwreck Costa Concordia - Emilia Romagna Earthquake (12043) Enrico Davoli (Italy)