



## **Com 5 - Positioning and Measurement Work Plan 2007- 2010**

**Rudolf Staiger  
Chair Elect Commission 5**

**29th General Assembly FIG Congress Munich, October 2006**

1



### **C5 – workplan 2007 2010 (FIG)**

#### **Term of reference**

- The science of measurement (instrumentation, methodology and guidelines)
- The acquisition of accurate and reliable survey data related to the position, size and shape of natural and artificial features of the earth and its environment and including variation with time.

2

## working groups

- **WG 5.1** Standards, Quality Assurance and Calibration
- **WG 5.2** Reference Frame in Practice
- **WG 5.3** Integrated Positioning, Navigation and Mapping Systems
- **WG 5.4** GNSS

## Com 5 – Liaison

### **FIG Commission 5 maintain cooperations with:**

- the International Association of Geodesy (IAG)
- the UN Office for Outer Space Affairs

### **future FIG Commission 5 exploring cooperation with:**

- Institute of Navigation (US)
- ISPRS

## **Com 5 – Open Meeting**

Monday, 9. October, 9 p.m  
ICM Room 21a

- **Send your National Delegates!!**
- **Invite all interested colleagues!!**